PO Summary - AB0502751

PO/Reference No. AB0502751

Supplier FIRETROL PROTECTION SYSTEMS INC

Gen	eral Information	Shipping Information	Billing/Payment
PO/Reference No.	AB0502751	Ship To	Bill To
Revision No.	8	Attn:	Tarleton State University-
Supplier Name	FIRETROL PROTECTION SYSTEMS	Central Receiving Bldg 508	Accts Payable ***Do Not Mail Invoice***
	INC	201 Saint Felix St	Email invoices to
Address	10320 MARKISON ROAD	Stephenville, TX 76401	invoices@tarleton.edu
	DALLAS, TX 752381648 US	United States	Box T-0120 Stephenville, TX 76402
Phone	+1 214-343-9200		United States
Purchase Order Date	12/3/2019	ShipTo Address Code 04-001	
Total	69,048.36 USD		
Requisition Number	126295277	Delivery Options	BillTo Address Code 04
Owner Business Unit	04-Tarleton State University (04)	Emergency (attach	
Order Category	1 - Regular	justification)	Billing Options
Report Reference A	no value	Ship Via Best Carrier-Best Way	Accounting Date 11/22/2019
Report Reference B	no value	Requested Delivery Date	Payment Terms 0, Net 30
Sole Source (attach	×		FOB / FREIGHT Destination
justification)		Buyer Information	Pre-Pay & Add
Contract Number	BUYBOARD 574-18	Buyer Buyer Email Buyer Phone	Special Payment Method no value
Start Date	no value	Number	
End Date	no value	dew - Whitten, whitten@tarleton.edu 254.968.9614	
Trade-In	×	Donald 234.300.3014	
Create Asset Manually	×	CC04	
Add to Asset Number	no value		
Cost Receipt Required	✓	Report Codes-1	
Rush the Pymt Process	×	Order Type USAS One USAS Two LDT Code	
Contact Information		no value no value no value no value	
Owner Name	Kenda Rasco		
Owner Phone		Report Codes-2	
Owner Email	RASCO@TARLETON.EDU	Contract Workforce	
		State Order Number no value	
		Non-Compliant X	
		Basis of Award Group Purchase - Competitively	
		bid Cooperative Contract	

			Bypass Dept Allocato	or Ye:	s				
	Distrik	oution Information					Constitution Informa	-4:	
Distribution Methods		oution information			C	f 4 t	Supplier Inform	ation	
		he method(s) indicated below			Supplier Into	rormation	no value		
•					Account Co	.de	no value		
Email (HTML Attachment) rmcknight@firetrol.net PO Revisions are NOT set to distribute for this PO				Pricing Cod					
PO Revisions are N	OT set to distribute for	or this PO			Quote num				
					_		no noto		
istribution Options				Note to Sup	•	no note			
Supplier Terms and Co	onditions				Attacnment	s for supplier			
		services performed as a will meet or exceed all exceptions to the pricin herein must be approved Department of Procure shipping.	specifications herein. ng or the description o ed by Tarleton State U	Any contained Iniversity's		o Collect Freight Chargo U - Vendor PO Conditio			
				Accounti	ng Codes				
Fiscal Year	Member ID	Department Code	Account Code	Report R	Reference C	Report Reference D	Object Code	Class Code	Special Routing1
2020	04 Tarleton State University	04-RISKM-00001 04-Environmental Health and Safety	04-200925-00000 Risk Management & Compliance Operat	no	value	no value	no value	no value	L Local
Accounting Codes \	Values vary by line.								
				Line Iten	n Details				
Product De	escription				Catalog No	Size / Packa	ging Unit Pric	e Quantity	Ext. Price
1 ✓ Annual Fire	e Alarm and Sprinkle	er inspections - E & G bu	ıildings 👺		na	EA	22,625.00 USI	D 1 EA 22	625.00 USD

Product Description Catalog No Size / Packaging Unit Price Quantity Ext. Price 1 ✓ Annual Fire Alarm and Sprinkler inspections - E & G buildings na EA 22,625.00 USD 1 EA 22,625.00 USD Taxable Capital Expense X Commodity Code 81141805 Building inspection service | 5670 Requisition Number 126295277 External Note no note Attachments for supplier

	✓	Annual Fire Alarm and Sprinkler inspections - Centennia	l Hall 👺	na	EA	880.00 USD	1 EA	880.00 USD
		Accounting Codes values have been overridden for this l	ine					
			Taxable	✓		Requisition Number	126295277	
			Capital Expense	×		External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	I	Attachments for supplier	r	
3	√	Annual Fire Alarm and Sprinkler inspections - Heritage I	Hall 👺	na	EA	3,285.00 USD	1 EA	3,285.00 USD
		Accounting Codes values have been overridden for this l	ine					
			Taxable	✓		Requisition Number	126295277	
			Capital Expense	×		External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	l	Attachments for supplier	r	
4	√	Annual Fire Alarm and Sprinkler inspections - Honors H	all 👺	na	EA	3,585.00 USD	1 EA	3,585.00 USD
		Accounting Codes values have been overridden for this	ine					
			Taxable	✓		Requisition Number	126295277	
			Capital Expense	x		External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	I	Attachments for supplier	r	
5	√	Annual Fire Alarm and Sprinkler inspections - Hunnewel	l Annex 👺	na	EA	550.40 USD	1 EA	550.40 USD
		Accounting Codes values have been overridden for this l	ine					
			Taxable	✓		Requisition Number	126295277	
			Capital Expense	x		External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	I	Attachments for supplier		

	Taxable	✓	Requisition Number	126295277	,
	Capital Expense	x	External Note	no note	
	Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	er	
✓ Annual Fire Alarm and Sprinkler inspections -	Integrity 🁺	na E <i>l</i>	3,585.00 USD	1 EA	3,585.00 USD
Accounting Codes values have been overridde	en for this line				
	Taxable	✓	Requisition Number	126295277	,
	Capital Expense	x	External Note	no note	
	Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	er	
✓ Annual Fire Alarm and Sprinkler inspections -	Legacy 👺	na E <i>l</i>	1,420.00 USD	1 EA	1,420.00 USD
Accounting Codes values have been overridde	en for this line				
	Taxable	✓	Requisition Number	126295277	7
	Capital Expense	×	External Note	no note	
	Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	er	
✓ Annual Fire Alarm and Sprinkler inspections -	Legends 👺	na E <i>l</i>	1,080.00 USD	1 EA	1,080.00 USD
Accounting Codes values have been overridde	en for this line				
	Taxable	✓	Requisition Number	126295277	,
	Capital Expense	x	External Note	no note	
	Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	er	

			Taxable	✓	Requisition Number	126295277	
			Capital Expense	x	External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	r	
1 🗸	Annual Fire Alar	m and Sprinkler inspections - Tradi	itions North and South	na E <i>A</i>	3,585.00 USD	2 EA	7,170.00 USD
	Accounting Co	odes values have been overridden for	this line				
			Taxable	✓	Requisition Number	126295277	
			Capital Expense	x	External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	r	
12 🗸	Annual Fire Alar	m and Sprinkler inspections - Vent	ure Apartments 👺	na EA	340.00 USD	1 EA	340.00 USD
	Accounting Co	odes values have been overridden for	r this line				
			Taxable	✓	Requisition Number	126295277	
			Capital Expense	×	External Note	no note	
			Commodity Code	81141805 Building inspection service 5670	Attachments for supplie	r	
I3 √	Annual Fire Alar	m and Sprinkler inspections - WK (Gordon Center 👺	na EA	510.00 USD	1 EA	510.00 USD
3 🗸		m and Sprinkler inspections - WK (_	na EA	510.00 USD	1 EA	510.00 USD
13 🗸			_	na EA		1 EA 126295277	510.00 USD
13 🗸			r this line		Factorial Note		510.00 USD
13 🗸			r this line Taxable	*	Requisition Number	126295277 no note	510.00 USD
	Accounting Co		Taxable Capital Expense Commodity Code	X 81141805 Building inspection service	Requisition Number External Note Attachments for supplie	126295277 no note	510.00 USD 810.00 USD
13 🗸	Annual Fire Alar	odes values have been overridden for	Taxable Capital Expense Commodity Code	X 81141805 Building inspection service 5670	Requisition Number External Note Attachments for supplie	126295277 no note r	

		Capital Expense	X		External Note	no note	
		Commodity Code	81141805 Building inspection service 5670		Attachments for supplier		
15	\checkmark Annual Fire Alarm and Sprinkler inspections - Dining H	łall 👺	na I	EA	710.00 USD	1 EA	710.00 USD
	Accounting Codes values have been overridden for thi	s line					
		Taxable	✓	ı	Requisition Number	126295277	
		Capital Expense	x	ı	External Note	no note	
		Commodity Code	81141805 Building inspection service 5670	,	Attachments for supplier		
16	✓ Annual Fire Alarm and Sprinkler inspections - Sports R	ecreation Facility 👺	na I	EA	640.00 USD	1 EA	640.00 USD
	Accounting Codes values have been overridden for thi	s line					
	<u>-</u>	Taxable	✓		Requisition Number	126295277	
		Capital Expense	×		External Note	no note	
		Commodity Code	81141805 Building inspection service 5670		Attachments for supplier		
17	✓ Annual Fire Alarm and Sprinkler inspections - Pressbo	к, New and Old 🁺	na I	EA	950.00 USD	1 EA	950.00 USD
	Accounting Codes values have been overridden for thi	s lino					
	Accounting codes values have been overhoden for this	Silile					
	Accounting codes values have been overridden for this	Taxable	✓		Requisition Number	126295277	
	Accounting codes values have been overridden for this		✓ x		Requisition Number External Note	126295277 no note	
	Accounting codes values have been overridden for this	Taxable	X 81141805 Building inspection service 5670	ı	•	no note	
18		Taxable Capital Expense Commodity Code	81141805 Building inspection service 5670	ı	External Note	no note	510.00 USD
18		Taxable Capital Expense Commodity Code	81141805 Building inspection service 5670	,	External Note Attachments for supplier	no note	510.00 USD
18	✓ Annual Fire Alarm and Sprinkler inspections - Police an	Taxable Capital Expense Commodity Code	81141805 Building inspection service 5670	EA	External Note Attachments for supplier	no note	510.00 USD

			Commodity Code	81141805 Building inspection service 5670	Attachments for supplier		
19	✓	E&G repairs - Ferguson Hall-Replace Horn base in #242 (\$ replace smoke in ice machine room (\$263)	280) and Physical Plant-	na EA	543.00 USD	1 EA	543.00 USD
			Taxable	✓	Requisition Number	127227049	
			Capital Expense	x	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
20	✓	Sports Medicine Demo old fire alarm devices that are not fire alarm system. (3) old smokes in storage room 104, Roroom 118,. One duct detector needs to be removed in back	om #113 hasone, One in	na EA	340.00 USD	1 EA	340.00 USD
		Accounting Codes values have been overridden for this line	9				
			Taxable	✓	Requisition Number	127227049	
			Capital Expense	×	External Note	no note	
			Capital Expense Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	External Note Attachments for supplier		
21	✓	Thompson Student Center - Replace (3) old Faraday pull st BG 12 pull stations	Commodity Code	99900294 Other Contracted Services - no specific comm code available	Attachments for supplier		387.00 USD
21	✓		Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		387.00 USD
21	~	BG 12 pull stations 🁺	Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		387.00 USD
21	√	BG 12 pull stations 🁺	Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670 na EA	Attachments for supplier 387.00 USD	1 EA	387.00 USD
21	✓	BG 12 pull stations 🁺	cations with new firelite Taxable	99900294 Other Contracted Services - no specific comm code available 5670 na EA	Attachments for supplier 387.00 USD Requisition Number	1 EA 127227049 no note	387.00 USD

			Taxable	✓	Requisition Number	127552721	
			Capital Expense	x	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
3	✓	TV 1&2 - repairs after annual sprinkler inspections - rebui	ild failed backflows 👺	na EA	1,310.00 USD	1 EA	1,310.00 USD
		Accounting Codes values have been overridden for this lin	e				
			Taxable	✓	Requisition Number	127552721	
			Capital Expense	x	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
24	✓	Legends - Manual pull in front lobby front of building wo tried	uld not go on the alarm	na EA	970.00 USD	1 EA	970.00 USD
		Accounting Codes values have been overridden for this lin	e				
		Accounting Codes values have been overridden for this lin	e Taxable	✓	Requisition Number	128334423	1
		Accounting Codes values have been overridden for this lin	I.	×	Requisition Number External Note	128334423 no note	ı
		Accounting Codes values have been overridden for this lin	Taxable			no note	
25	✓	Accounting Codes values have been overridden for this line. Tarleton Center - Need to replace smoke on second floor Bender Hall - Will need to trouble shoot the smoke detect the smoke went in alarm but horns did not sound.	Taxable Capital Expense Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	External Note Attachments for supplier	no note	1,762.00 USD
25	√	Tarleton Center - Need to replace smoke on second floor Bender Hall - Will need to trouble shoot the smoke detect	Taxable Capital Expense Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	External Note Attachments for supplier	no note	1,762.00 USD
25	√	Tarleton Center - Need to replace smoke on second floor Bender Hall - Will need to trouble shoot the smoke detect	Taxable Capital Expense Commodity Code in office for data center & tor in rooms 103 and 303.	99900294 Other Contracted Services - no specific comm code available 5670	External Note Attachments for supplier 1,762.00 USD	no note	1,762.00 USD
25	✓	Tarleton Center - Need to replace smoke on second floor Bender Hall - Will need to trouble shoot the smoke detect	Taxable Capital Expense Commodity Code in office for data center & tor in rooms 103 and 303.	99900294 Other Contracted Services - no specific comm code available 5670 na EA	External Note Attachments for supplier 1,762.00 USD Requisition Number	no note 1 EA 128334423 no note	1,762.00 USD

				Taxable	✓	Requisition Number	128334423	
				Capital Expense	×	External Note	no note	
				Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier	no note	
7	V		Heritage-In room 4034CD replace bas horn. In rooms 4021 horns from smoke base not working. Also replace speaker		na EA	927.00 USD	1 EA	927.00 USD
		0	$ lap{3}{ m Accounting}$ Codes values have been overridden for this line	2				
				Taxable	✓	Requisition Number	128334423	
				Capital Expense	x	External Note	no note	
				Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
28	~	5	Pressbox New and Old - Fire Alarm s - \$340 each. Correctionsystem of new stadium not included in original specs		na EA	340.00 USD	2 EA	680.00 USD
		U	Accounting Codes values have been overridden for this line					
				Taxable	✓	Requisition Number	128873018	
				Capital Expense	x	External Note	no note	
				Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
								494.00 USD
29	~		Bender Hall - Install (2) Sounder based to remove red tag - \$154 and Labor = \$340 酔	· Alarm equipment =	na EA	494.00 USD	1 EA	494.00 03D
29	~				na EA	1		454.00 030
29	~			Alarm equipment = Taxable Capital Expense	na EA	494.00 USD Requisition Number External Note	1 EA 129831578 no note	494.00 03D

)	✓	Heritage Hall - Replace Additional wall mount speaker stro Labor = \$340	be Equipment = \$61 and	na EA	401.00 USD	1 EA	401.00 USD
		Accounting Codes values have been overridden for this line					
			Taxable	✓	Requisition Number	129831578	
			Capital Expense	×	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
1	✓	Honors Hall - Troubleshoot Nac 3&4 on power supply 🃑		na EA	680.00 USD	1 EA	680.00 USD
		Accounting Codes values have been overridden for this line					
			Taxable	✓	Requisition Number	129831578	
			Capital Expense	x	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
2	✓	REPLACE PACKING ON FIRE PUMP AT TRADITIONS SOUTH	- <u>j</u>	na EA	760.00 USD	1 EA	760.00 USD
		Accounting Codes values have been overridden for this line					
			Taxable	✓	Requisition Number	131075568	
			Capital Expense	×	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available 5670	Attachments for supplier		
33	√	REPLACE SOLENOID ON DELUGE SYSTEM AT O A GRANT B	LDG 👺	na EA	328.36 USD	1 EA	328.36 USD
			Taxable	✓	Requisition Number	131075568	
			Capital Expense	x	External Note	no note	
			Commodity Code	99900294 Other Contracted Services - no specific comm code available	Attachments for supplier		

					5670				
4	~		E&G repairs - Howell-remove smoke in Room 105E (\$255) detector not shutting down AC unit in basement (\$680)		na	EA	935.00 USD	1 EA	935.00 USD
				Taxable	✓		Requisition Number	131188521	
				Capital Expense	×		External Note	no note	
				Commodity Code	99900294 Other Contracted Serv specific comm code at 5670		Attachments for supplier		
5	~	/ H	Hunewell - Troubleshoot ground fault on power supply	•	na	EA	680.00 USD	1 EA	680.00 USD
		0	Accounting Codes values have been overridden for this lin	e					
				Taxable	✓		Requisition Number	131188521	
				Capital Expense	×		External Note	no note	
				Commodity Code	99900294 Other Contracted Serv specific comm code at 5670		Attachments for supplier		
5	√	/ F	Ferguson-replace manual pull 🁺		na	EA	290.00 USD	1 EA	290.00 USD
				Taxable	✓		Requisition Number	131188521	
				Capital Expense	×		External Note	no note	
				Commodity Code	99900294 Other Contracted Serv specific comm code av 5670		Attachments for supplier		
			Handling, and Tax charges are calculated and charged by each	n supplier. The values show	vn here are for estimation	purposes, t	oudget Subtotal Shipping		69,048.36 0.00
							Handling		0.00
									0.00